

# Download 2004 Audi A4 Coolant Temperature Sensor Manual

2003 Passat 1.8T Replaced Temp sensor per code P0117 and hard starts. Noticed that the housing that holds the sensor from above the u shaped clip to just below it is cracked. Audi Diagnostic Trouble Codes DTC Table - General: From model year 1996, vehicles manufactured for the North American market are equipped with a Government required diagnostic system known as On-Board Diagnostics II (OBD II). Audi A4 Quattro Digital Display on Instrument Cluster May Fail - 68 reports. Learn about this problem, why it occurs, and how to fix it. PAGE DISCLAIMER: The information below is 'General Information' and should be used as a guide. The Audi motor oil information on these pages should not be used as a substitute for what your vehicle owner's manual, factory service manual, or authorized Audi dealer recommends.